


SGS ITALIA S.p.A.

Industrial Services
Via G. Gozzi, 1/A
20129 Milano
Tel. (02) 7393.1 Fax: (02) 70125067
Affiliate code 095103



Pagina 1 di 2
Page of

CERTIFICATO D'ISPEZIONE No. 8206/MI
INSPECTION CERTIFICATE No.

Data: 22/07/14
Date

FILE NO. 14.9143mf/sl

FORNITORE
SUPPLIER LEGHORN SRL - VIA DEGLI ARROTINI 34/36 - LIVORNO

COSTRUTTORE
MANUFACTURER: LEGHORN SRL - VIA DEGLI ARROTINI 34/36 - LIVORNO

DESCRIZIONE MATERIALE:
MATERIAL DESCRIPTION
PRODOTTO SOTTOPOSTO ALL'ATTIVITA'
Sigillo a cavo "CABLESEAL 4,00 mm"

DOCUMENTI DI IDENTIFICAZIONE: LEGHORN DRAWINGS

ISPEZIONE ESEGUITA:
INSPECTION PERFORMED:

EFFETTUAZIONE DELLE PROVE DI ANTIMANOMISSIONE DEL SIGILLO DI ALTA SICUREZZA
CABLESEAL 4,00 mm PREVISTE DALLA NORMA ISO 17712:2013 punto 6) Annex A.

DOCUMENTI DI RIFERIMENTO:

Le prove effettuate sul materiale sono state eseguite in conformità con i seguenti documenti:
REFERENCE DOCUMENTS
Activities have been performed according to the following documents:

- NORMA ISO 17712:2013 punto 6) Annex A
- MANUFACTURER /PROVIDER TAMPER EVIDENCE PROGRAM DATED 29-04-14;
- LEGHORN TEST REPORT NO. 0005-2014
- CONFORMITY CERTIFICATE NO. 10531
- SGS INSPECTION REPORT NO. 14.500.0570 DATED 03-07-14

Member of SGS (Société Générale de Surveillance) Group

Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/laboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safely and readily accessible portions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s), in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

Member of the International Federation of Inspection Agencies Limited, London.



FT 06/12

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf.
The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.


Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

SGSPAPER
14783568



SGS ITALIA S.p.A.

Industrial Services
Via G. Gozzi, 1/A
20129 Milano
Tel. (02) 7393.1 Fax: (02) 70125067
Affiliate code 095103



CERTIFICATO D'ISPEZIONE No. 8206/MI

INSPECTION CERTIFICATE No.

Data: 22/07/2014

Date:

FILE NO. FILE NO. 14.9143mf/sl

Pagina 2 di 2
Page of

RISULTATI:

I risultati ottenuti dalle verifiche e dai collaudi effettuati sono riportati in dettaglio nei seguenti documenti:

TEST RESULTS

The test results of the activities performed are detailed in the following documents

Per witness:

For witness

- LEGHORN Rapporto di prova NO. 0005-2014

CONCLUSIONI

CONCLUSIONS

Le prove di antimanomissione effettuate sono risultate, per le attività eseguite, conformi ai requisiti dei documenti di riferimento e in particolare alla norma ISO 17712:2013 punto 6) Annex A

The appropriate testing activities have been performed and the results conform to the requirements outlined in ISO 17712 :2013 Clause 6 and Annex A

SGS Italia S.p.A.


On behalf of Sales Manager

Stefano Salvati

Member of SGS (Société Générale de Surveillance) Group

Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test/laboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safely and readily accessible portions of the consignment only. *Solely for services related to witnessing/observing a third party's intervention(s)*, in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.

Member of the International Federation of Inspection Agencies Limited, London.



FT 06/12

This document is issued, on the Client's behalf, by the Company under its General Conditions of Service printed overleaf. The Client's attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any other holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Clients instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents.

SGSPAPER

14783561

